

Product Safety Recall



Steelcraft One2 V2



Britax One2

Steelcraft One2V2 & Britax One2 Strollers

Series Numbers RM-S287T and RM-S287T-A

Sold through Baby Bunting NZ between 1/1/2024 and 6/10/2025

Defect: The handles may detach from these strollers due to missing rivets, and the operator may lose control.

Hazard: Risk of serious injury or death to children if the operator loses control of the stroller while in use.

What to do:

1. Stop using affected strollers immediately.
2. Contact Britax to arrange to have the stroller inspected and repaired if necessary.

Contact details:

phone: 0508 688 822

email: Recall-ANZ@britax.com

online: britax.co.nz

New Zealand Importer/Distributor

Britax Childcare New Zealand Ltd
The Crate - Flexible Office Space
28-30 Constellation Drive
Rosedale, Auckland
New Zealand 0632

See www.recalls.govt.nz for
other New Zealand consumer product recalls